

Shiny
NICKEL
Ice Machine Cleaner

SHINY NICKEL is a non-foaming, non-fuming cleaner that quickly removes scale from stainless steel and nickel plated steel. Contains special inhibitors to minimize corrosion, while effectively cleaning scale from all metal surfaces. SHINY NICKEL is USDA approved for use in federally inspected meat and poultry plants. Removes built-up lime scale eliminating the cause of equipment jamming and improves ice quality and capacity.

DIRECTIONS: Turn off ice machine. Drain water reservoir and refill with fresh water, adding 3 ounces of SHINY NICKEL per gallon of water. Start water circulating pump only and run 15-30 minutes. Use a brush to apply cleaner to scaled surface not adequately contacted by circulating solution. If scale is extra heavy, drain and repeat the cleaning procedure. After scale has been removed, drain and flush at least 2 or 3 times. For stainless steel ice machine drums, add 8 ounces of cleaner per one gallon of water in a plastic container and brush the solution on the scaled areas. After cleaning flush all surfaces thoroughly with fresh water.

MODO DE EMPLEO: Apague la máquina de hielo. Desagüe el agua del depósito y llene de nuevo con agua fresca, agregando 3 onzas de SHINY NICKEL por galón de agua en el sistema. Empiece la bomba calculadora de agua solamente y deje que corra 15-30 minutos. Use un cepillo para aplicar la solución. Si escala es extra pesada, desagua y repite el procedimiento de limpieza. Después que la escama ha sido removida, desagüe el sistema y repita 2 o 3 veces. Para la máquina de hielo de acero inoxidable golpetea, agrega 8 onzas de limpiador por un galón de agua en un contenedor plástico y cepilla la solución en las áreas escaladas. Después de limpiar limpia todas las superficies completamente con agua fresca.

CONTAINS (CAS#): Phosphoric Acid (7664-38-2), Water (7732-18-5), Citric Acid (77-92-9). For more ingredient information visit www.questspecialty.com

HMIS RATINGS: Health - 3, Flammability - 0, Reactivity - 0, Personal - B.

Made in USA

NSF

Nonfood Compounds
A3

QuestSpecialty

Shiny
NICKEL
Ice Machine Cleaner
Limpiador de Máquina de Hielo

Quickly Removes Lime Scale
Protects Nickel Plated & Stainless Steel

DANGER/PELIGRO
CAUSES SEVERE SKIN BURNS AND EYE DAMAGE.
CAUSA QUEMADURAS GRAVES EN LA PIEL Y LESIONES OCULARES.

NET CONTENTS: ONE GALLON (3.8 L)

QuestSpecialty Corporation
P.O. Box 624 • Brenham, TX 77834
800.231.0454 • www.questspecialty.com

SDS AND
PRODUCT INFO



Shiny
NICKEL
Ice Machine Cleaner

DANGER: Causes severe burns and serious eye damage. Do not breathe mists. Wash hands thoroughly after handling. Wear protective gloves and eye protection. If swallowed: Rinse mouth. Do NOT induce vomiting. If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water or shower. Wash contaminated clothing before reuse. If inhaled: Remove person to fresh air and keep comfortable for breathing. Immediately call a poison center or doctor. If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

PELIGRO: Causa quemaduras graves en la piel y lesiones oculares grave. No respire los vapores. Lávese bien las manos después de manipular. Use guantes y protección para los ojos. En caso de ingestión: Enjuague la boca. NO induzca vomito. Si en la piel (o el pelo): Quitese inmediatamente la ropa contaminada. Enjuague bien con agua. Lave la ropa contaminada antes de usar. Si es inhalado: Remueva la persona al aire fresco y mantenga cómoda para respirar. Inmediatamente llame al centro de envenenamiento o al médico. Si en los ojos: Enjuague cuidadosamente con agua por varios minutos. Remueva los lentes de contacto, si están presentes y fáciles de hacer. Continúe enjuagando.

STORAGE: Store locked up. Dispose of contents and container in accordance with local, state, and national regulations. Use or store with adequate ventilation. Do not transfer to unmarked container. Keep container closed. Empty container may contain hazardous product residues. Loosen closure carefully. Do not expose to heat or store at temperatures above 120°F. KEEP FROM FREEZING.

ALMACENAJE: Guarde bajo llaves. Elimine el contenido y el recipiente de acuerdo con las ordenanzas locales, estatales, y reglamentos nacionales. Use o almacene con ventilación adecuada. No transfiera a un envase no marcado. Mantenga el envase cerrado. Envase vacío puede contener residuo peligroso. Afloje la cerradura con cuidado. No exponga al calor o almacene a temperaturas por encima de 120°F. EVITE QUE SE CONGEELE.

ITEM 666200001-41GL

600000356

